



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6128		Stuart	AVE

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	4000	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 21

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0021.JPG

**Image Status:** Image found and displayed.



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0022.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2615		Taney	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50	

**Comments:**

## SMOKE TEST PHOTOS




**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0015.JPG

**Image Status:** Image found and displayed.



**Photo No:** 17

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0017.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2615		Taney	ROAD

<b>Source Type:</b>	05= Downspout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	350	

**Comments:**

## SMOKE TEST PHOTOS




**Photo No:** 16

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0016.JPG

**Image Status:** Image found and displayed.



**Photo No:** 17

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0017.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2600		Taney	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 18

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0018.JPG

**Image Status:** Image found and displayed.



**Photo No:** 19

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0019.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2607		Taney	ROAD

<b>Source Type:</b>	09= Stairwell Drain	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 20

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0020.JPG

**Image Status:** Image found and displayed.



**Photo No:** 21

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0021.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2700		Taney	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	80	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0022.JPG

**Image Status:** Image found and displayed.



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0023.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2705		Taney	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0024.JPG

**Image Status:** Image found and displayed.



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0025.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	Y
<b>Defect No:</b>	7	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2702		Taney	ROAD

<b>Source Type:</b>	14= Catch Basin	<b>Location:</b>	6=Curb	<b>Severity:</b>
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	4200	

**Comments:**

## SMOKE TEST PHOTOS




**Photo No:** 26

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0026.JPG

**Image Status:** Image found and displayed.



**Photo No:** 27

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0027.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


<b>Unique Test ID</b>	183	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	8	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2700		Taney	ROAD

<b>Source Type:</b>	05= Downspout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	350	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 28

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0028.JPG

**Image Status:** Image found and displayed.



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0023.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 183

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\183.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6101		Stuart	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>
---------------------	------------------	------------------	-------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50
----------------	-----------	-----------------------	----

**Comments:** holes in ground

## SMOKE TEST PHOTOS



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0023.JPG

**Image Status:** Image found and displayed.



**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0024.JPG

**Image Status:** Image found and displayed.



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID184-A1\2005\_0519Image025.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 184

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2604		Steele	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 25

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0025.JPG

**Image Status:** Image found and displayed.



**Photo No:** 26

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0026.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 184

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2600		Steele	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 27

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0027.JPG

**Image Status:** Image found and displayed.



**Photo No:** 28

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_A\A\_2004\_1007Image0028.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 184

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2605		Steele	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 29

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0029.JPG

**Image Status:** Image found and displayed.



**Photo No:** 30

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0030.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 184

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6011		Stuart	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0	

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 31

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0031.JPG

**Image Status:** Image found and displayed.



**Photo No:** 32

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0032.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



**Sketch No:** 184

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	184	<b>Date:</b>	10/7/2004	<b>MeterBasin:</b>	01_WR17A
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6011		Stuart	AVE

<b>Source Type:</b>	18= Other	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>
---------------------	-----------	------------------	-------------	------------------

<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	50
----------------	-----------	-----------------------	----

**Comments:** hole

## SMOKE TEST PHOTOS



**Photo No:** 31

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0031.JPG

**Image Status:** Image found and displayed.



**Photo No:** 32

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1007-2004\T-1\PLAYER\_B\B\_2004\_1007Image0032.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 184

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\184.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*